

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**FV884**  
**NE**  
**> 1**  
**1.186 mi.**  
**6263 ft.**

**MANHOLE 73122**  
**OCEAN PKWAY & AVENUE W**  
**BROOKLYN, NY**

**NY Spills** **S108296053**  
**N/A**

**Site 2 of 3 in cluster FV**

**Relative:**  
**Higher**

**SPILLS:**

**Actual:**  
**12 ft.**

Name: MANHOLE 73122  
Address: OCEAN PKWAY & AVENUE W  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 0609416 / 2007-03-19  
Facility ID: 0609416  
Facility Type: ER  
DER Facility ID: 323386  
Site ID: 373648  
DEC Region: 2  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2006-11-15  
Investigator: GDBREEN  
Referred To: Not reported  
Reported to Dept: 2006-11-15  
CID: 78  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2006-11-16  
Spill Record Last Update: 2007-03-19  
Spiller Name: Not reported  
Spiller Company: CON EDISON  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: ERTS  
DEC Memo: "03/19/07 - See e-docs for Con Ed report detailing cleanup and closure. 20339. see eDocs"  
Remarks: "2 qts dielectric fluid in 200gal of water in earthen sump clean-up pending ref # 203339 "

**All Materials:**

Site ID: 373648  
Operable Unit ID: 1131350  
Operable Unit: 01  
Material ID: 2121046  
Material Code: 0541A  
Material Name: dielectric fluid  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported